



# Aged Concrete Poles

Michael Whaley, Powerco

21 June 2017

# Situation

## June 2016:

- Incident near Morrinsville where a concrete pole failed while a line mechanic was working on the pole from a ladder.
- The line mechanic was unbinding the LV conductors adjacent to a car v pole work site. The line mechanic sustained injuries as a result of the incident.
- Investigation found that the pole had been damaged just below ground level, possibly as a result of the car damage, that cause structural damage to the pole.
- Believed that pole failed under the combined weight of the mechanic, his tools and the ladder after the LV wires were unbound.

## Valley 9 pole

- The pole type is commonly referred to as the Valley 9 – a 9 metre long prestressed concrete pole often found in the Morrinsville area.
- Early versions of the pole have four 7 mm high tensile steel bars with four 5 mm diameter high tensile tendons.
- Later versions have four 9.6 mm diameter pretensioned steel cables.
- Generally made in the late 1950s and 1960, then manufacturer was taken over by Firth.

# Pole location

Position of pole (pre-incident)  
South facing





Broken butt (at incident scene, pole removed)



Broken pole and butt (at incident scene)

# Post Incident Investigation

Gathered six  
Valley 9 poles  
for structural  
testing

Tested 3 in  
Down Line  
direction  
and 3 in  
Cross Line  
direction at  
Buscks  
pole  
breaking rig

Analysed  
results

Recommendations  
about climbing and  
replacement

# Cross line pole testing



# Down line pole testing



# Down line pole testing





## Down line pole testing



## Below ground line tendon defect on I0888



## Below ground line tendon defect close up



## Below ground line tendon defect became point of breakage



# Damaged tendon at ground line on pole 10885



Photo: Ron Coleman

# Damaged tendon at ground line on pole 10885



# Damaged tendon became point of breakage




# Testing results summary

| Test ID              | Pole ID | Cast Date                       | Age       | Test Orientation | Breaking Load (kgf) | Deflection (mm) | Comments                            |
|----------------------|---------|---------------------------------|-----------|------------------|---------------------|-----------------|-------------------------------------|
| <b>Valley 9 Pole</b> |         |                                 |           |                  |                     |                 |                                     |
| PC81                 | I1114   | 1962                            | 55 years  | Down Line        | 240                 | 1065            |                                     |
| PC79                 | I0886   | 1958                            | 59 years  | Down Line        | 240                 | 830             |                                     |
| PC77                 | I0885   | 1998 ???<br>More likely<br>1958 | 59 years? | Down Line        | 180                 | 655             | Chip exposing tendon at ground line |
| PC82                 | I0888   | 1968                            | 49 years  | Cross Line       | 580                 | 380             | Exposed tendon below ground line    |
| PC78                 | I0883   | 1968                            | 49 years  | Cross Line       | 740                 | 750             |                                     |
| PC80                 | I0884   | 1960                            | 57 years  | Cross Line       | 810                 | 1200            |                                     |




## Valley 9 Pole Breaking Characteristics




# Comparison – Normal & Students T (DoF = 2) Distributions


## Benefit of having adequate sample size




# Testing results summary



# Downline pole strength



# Cross Line Pole Strength



# Conclusions

## What we've found:

- Some differences exist in approach between AS/NZS7000 (Table 8.1) (minimum strength within a sample) and Students T distribution on pole strength samples (average strength in series of samples).
- We don't have enough pole strength samples for this particular pole type
- Our GIS information does not distinguish between different pole types apart from material and height so identifying these poles needs to be done as part of routine inspection and line crew education.
- The statistical analysis shows that we need to take the concern over aged concrete pole strength seriously.
- Many of the points of weakness in the poles are not able to be easily identified (for instance, it is not normal to have to dig around a concrete pole to assess its strength)
- Given the uncertainties, we are doing proactive replacement of these poles. The proactive replacement will us help to undertake more testing.
- In the mean time, a pragmatic approach is to allow climbing under certain circumstances for the purpose of undertaking limited activities like fuse replacement. Otherwise access to these poles needs to be via elevated work platform or with the pole properly supported.

## The End

For more information about Powerco visit our Facebook page or  
[www.powerco.co.nz](http://www.powerco.co.nz)