

Incident Title:

Access to LV of kiosk while energised

Date of Incident:

Wednesday 27th June 2018

Incident Description and Details:

The BoP operator proceeded to unlock the LV 690v double doors of a TX Kiosk and then stood back, took a photo of the bushing, closed the double doors and locked the LV door.

Signage in the LV area states that the LV doors must not be opened unless transformer has been isolated and earthed, this was not followed.

At no time did the BoP operator encroach the MAD of 150mm.

Recommendations / Lessons:

Correct operating procedures and signage need to be followed always.

If there is any doubt or if unsure about the task STOP Take 5 and contact your supervisor for clarification.

HSE Advisor


Cliff George

Contact Person:


Garry Blake Delivery Manager, 027 471 4667



Double access doors with locks



Exposed bushings with 690 V cable terminations inside double doors



Layout of kiosk LV doors opening out and the location the BoP operator was standing while taking a photo at approx 1m.