

Evantair Oscillating Fan – Fan Blade Failure

Incident:

Two separate incidents have occurred in our Greenlane office where Evantair oscillating fan blades have shattered / exploded when turned on. The broken blade becomes a projectile and can cause injury.

These fans have been brought into the office by employees and are not suitable for a commercial environment.



Action:

Site Use

1. Remove Evantair fans immediately from service

Home use

2. Check the blades before use
 - a. Ensure that the blades are running freely and are balanced
 - b. Ensure that there are no cracks in the blades
 - c. Ensure that there is no degradation or powdering of the blades
 - d. If in doubt do not use
3. Share this alert with friends and family

For further information about this safety notification, please refer to Synergi Life incident #'s 16088, 15803, or contact Ursula van den Bosch on 027 809 6220.

Date issued: 08/02/2019

Please discuss this Safety Alert with workers at your next tool box or team meeting