

## Shared Learning





















Reference to Critical Risk where appropriate







# Medical Treatment Injury whilst using Drill Press

### What happened?

- 1. The IP (injured party) was using the drill press at the Station mechanical workshop to drill cable plates for a new 400v cabinet.
- 2. The IP didn't clamp the plate to the drill press resulting in it spinning around whilst drilling
- 3. The edge of the metal plate caught the IP on the hand and finger, resulting in 5 stitches.

#### Karapiro Hydro Station - Mercury

#### What did we learn?

- Checks are necessary to ensure workers are competent and not just trained in using specialised equipment.
- 2. A Safe Work Procedure attached to the machine may have ensured that the clamping of the metal plate occurred prior any drilling taking place
- 3. Pre-start meetings need to include discussions around specialised equipment and competency.
- 4. Anything being drilled will be clamped securely in place



