



# Safety Alert



## INCIDENT TITLE:

1296817-Found damaged equipment has been put back in service.

## TIME AND DATE OF INCIDENT:

29 Aug 2022 : 11:00AM

## INCIDENT DETAIL :

While completing the major service at WHL47, the team set up to carry out the accumulator gas pressure and top-up checks.

It was found that the test gear, the hose, and regulator was damaged and was known to be a condemned unit that had already been taken out of service.

The test gear had previously been removed from the turbine service kit and placed on the workshop bench while a new kit was being ordered.

## IMPORTANT INFORMATION:

- Although discussed that the gear was not suitable for use the gear was not tagged.
- The gear was left on the bench and not placed in the quarantine bin.
- It was believed the physical state of the equipment showed it was not fit for use.

## BEST PRACTICE:

- All tools and equipment are checked before taken to the work site.
- Faulty equipment is tagged out and placed in quarantine bin.

## PHOTO



## IMMEDIATE INTERIM ACTIONS:

- Put a stop to the accumulator checks.
- Faulty equipment disassembled and thrown out for second time.

## REMINDER:

Always use an Out of Order tag when discarding gear or alternatively destroy the gear beyond repair.

THIS SAFETY ALERT HAS BEEN ISSUED BY THE HEALTH & SAFETY TEAM. FOR FURTHER INFORMATION PLEASE CONTACT:

Steve Herbst Health and Safety Business Partner Hydro 021 227 0059

Steve.Herbst@meridianenergy.co.nz