



# Heads Up

**SAFETY  
ALERT**

## **WHERE & WHEN:**

Huntly Power Station, ID Fan area, 4<sup>th</sup> April 2018

## **WHAT HAPPENED?**

One of our Team members was walking across to Unit 6 when the ground gave way beneath him revealing a small tomo. This fall twisted his back and knee; thankfully not badly enough to cause a major injury. The hole had running water in it which identified as the cause for the ground to be undermined. The water was confirmed to be a domestic water leak.

## **WHAT COULD HAVE HAPPENED?**

If things had gone differently the Team member could have sustained an injury with long term consequences.

## **WHAT ARE WE DOING?**

Investigating water losses from pressure systems and identifying and fixing any further water leaks.

## **YOUR INPUT & ACTION REQUIRED**

- Watch where you are walking
- Look for any ground deformation
  - Flag it immediately to Operations for investigation
  - Put hazard barriers in place to prevent access and potential injury



**THANKS FOR YOUR COMMITMENT TO A SAFER WORKPLACE**