


Chain Wheel Retainer and Chain fell 5 metres



Picture above indicates the distance where the chain and retainer fell from height of approx. 5m.

Resting position of chain and chain retainer on concrete floor.

SYNERGI LIFE - REFERENCE NUMBER: 17026

When and Where this happened:

11th July 2019 Kawerau Power Station.

Brief Description of Incident:

While employee was using a chain wheel and chain to close a valve, the chain wheel retainer and chain came loose from the wheel and fell 5m resting approximately 1m from the employee, no-one was injured during the event.

IMMEDIATE ACTIONS:

1. Contractors engaged to check and tighten all other chain wheels on this site
2. Advice out to other sites to check the same
3. Safety Alert out to industry peers via StayLive
4. Incident Investigation underway – any further learnings to be shared post investigation

For further information about this safety notification, please refer to Synergi Life incident # 17026, or contact Jordan Jones – Kawerau Maintenance Team Leader or Jason Pore H&S Manager

Date issued: 15/7/2019