



FIRST ALERT

3 February 2021


Fall from height

Whilst undertaking blasting work on a tower on the OTB-HAY A line, a Tower Painter has been involved in a fall from height.

The worker was rescued by other members of the work crew and the emergency services were called.

The worker received medical attention on site and was taken to hospital for further precautionary checks. He was discharged later that day.

An Investigation has commenced.



Immediate actions

- When undertaking any working at height operations reinforce the following with your teams:
 - Ensure that the equipment you use is fit for purpose.
 - All safety equipment is certified, inspected prior to and following use, and has a current valid test.
 - Ensure all people working at height maintain and comply with working at height procedures.
- Further details regarding the incident will be provided once the investigation has been completed.

For more information, please contact:

Name	Danny Kooyman
Position	H&S Practitioner
Mobile	0212283986
Email	danny.kooyman@transpower.co.nz
Maximo ref	129846
Incident date	02/02/2021

