



FIRST ALERT

21 May 2021

Worker slipped while carrying out vegetation work

On 18th May 2021 while engaged in vegetation work cutting maximum sag trees within a span, an ElectroNet worker lost his footing and fell down a steep slope. During the fall, his face struck an object resulting in a laceration to the side of his face.

The worker was taken to hospital and the laceration required 30 stitches.

An investigation into the incident is underway.



For more information, please contact:

Name	Robyn Scott
Position	Health and Safety Co-ordinator
Mobile	027 516 0075
Email	rscott@electronet.co.nz
Maximo ref	18 th May 2021
Incident date	131509

